

Photographs



Image 1: Northwest-facing image of the Book House showing the structure’s disrepair and roof collapse (Roman Catholic Diocese of Hamilton, 2018).



Image 2: A closer view of the front façade showing the remains of the roof and plywood covered windows and door. The owners erected a barbed wire fence perimeter around the building sometime after 2010 (RCDH, 2018).



Image 3: The building has seen multiple instances of vandalism, such as graffiti as can be seen here on the northeast corner. Failing masonry and crumbling mortar is also visible throughout the walls (RCDH, 2018).



Image 4: In 2010, HMHC member Sylvia Wray conducted a site visit of the property. This image of the northeast corner shows the structure from the east (Wray, 2010).



Image 5: View of one of the property’s crumbling outbuildings in 2010 (Wray, 2010).



Image 6: View of what appears to be the remains of the same structure in 2018 (RCDH, 2018).



Image 7: The property contains an early or original one-storey brick wing, likely built as a kitchen, with a large chimney (Wray, 2010).




Image 8: View of the front of the kitchen wing section, showing plywood secured to the front to prevent illegal entries (Wray, 2010).



Image 9: The Book House as photographed in 2010 (Wray, 2010).



Image 10: The Book House as photographed in 2018 (RCDH, 2018).