# Appendix "C" to Report PED23187 Page 1 of 16

#### Photographs

(all images taken July 26, 2023 by City of Hamilton, unless otherwise stated)



7 Ravenscliffe Avenue, front (west) elevation and walkway



Northwest elevation



Southwest elevation



Southeast elevation showing the covered south side porch



Rear (east) elevation



Looking northeast on Ravenscliffe Avenue towards 5 Ravenscliffe Avenue



Looking southeast on Ravenscliffe Avenue



Closeup of hipped roof dormers with red clay tiles



Closeup of paired bracketed eaves, moulded frieze, and copper downspout

### Appendix "C" to Report PED23187 Page 6 of 16




Closeup of balconet with wrought-iron railings, corbels, and decorative keystones

### Appendix "C" to Report PED23187 Page 7 of 16




Closeup of coal chutes



Closeup of exterior carved wood door with acorn and leaf detail

### Appendix "C" to Report PED23187 Page 8 of 16



Wood paneled front foyer with cross vaulted ceiling, carved wood pilasters, and double brackets

### Appendix "C" to Report PED23187 Page 9 of 16



Front foyer, closeup of carved wood door and frame



Oval shaped dining room

# Appendix "C" to Report PED23187 Page 10 of 16



Closeup of wood paneling in dining room (Homeowner, 2021)



Closeup of the dining room wood carved crown moulding with dentils and ceiling plaster decoration

#### Appendix "C" to Report PED23187 Page 11 of 16



Wood paneled library (Homeowner, 2021)



Closeup of library wood carved crown moulding with dentils and plaster ceiling rosette

### Appendix "C" to Report PED23187 Page 12 of 16




Closeup of library carved wood fireplace with marble detailing

# Appendix "C" to Report PED23187 Page 13 of 16



Closeup of library plaster ceiling decorations

# Appendix "C" to Report PED23187 Page 14 of 16



Main staircase carved wood newel post

### Appendix "C" to Report PED23187 Page 15 of 16



Second-floor stairway alcove with carved wood keystone, fluted pilasters, and fluted Tuscan columns

### Appendix "C" to Report PED23187 Page 16 of 16



Closeup of carved wood handrail and paneling in second-storey of main stairway