

Photo-Documentation of 535 Old Dundas Road, Ancaster
(All photographs taken by City staff on November 6, 2023)



Figure 1: View of Front (East) Elevation facing Old Dundas Road



Figure 2: View of South Elevation along Ontario Road



Figure 3: View of Two Level Shed in rear yard



Figure 4: View of existing contemporary side garage



Figure 5: View of damage to shed foundation



Figure 6: View of deteriorating window frames with contemporary replacement windows



Figure 7: Views of damage to front porch ceiling



Figure 8: Detail View of damage to eaves



Figure 9: View of deterioration to wooden storm window



Figure 10: View of South Exterior and partially-collapsed side porch



Figure 11: Detail View of damage to side porch



Figure 12: View of contemporary side addition and foundation



Figure 13: View of typical interior



Figure 14: View of stone foundation wall in basement



Figure 15: View of foundation wall in basement, looking into side addition



Figure 16: View of deterioration of upper-storey wood windows



Figure 17: View of interior (left) and front exterior (right) wood doors



Figure 18: Early twentieth-century windows on front exterior



Figure 19: View of front porch with posts, scroll work and railings



Figure 20: Close-up view of scroll work



Figure 21: View of turned railings on front porch



Figure 22: View of property looking south along Old Dundas Road



Figure 23: View of property looking north along Old Dundas Road