

Photographs

All images taken by City of Hamilton on November 14, 2023, unless otherwise noted.



Figure 1: Front Elevation of Brick Farmhouse



Figure 2: Side (West) Elevation of Brick Farmhouse



Figure 3: Side (West) Elevation of Farmhouse showing Porch and Frame Kitchen



Figure 4: Rear of West Elevation of Farmhouse



Figure 5: Rear (South) Elevation of Farmhouse



Figure 6: Rear of West Elevation of Farmhouse



Figure 7: West Elevation of Farmhouse



Figure 8: Quarter-Circle Windows on West Elevation of Farmhouse



Figure 9: Detail view of windows, stone foundation, and projecting quoins



Figure 10: Detail View of Main Entrance of Farmhouse



Figure 11: Detail of scrollwork on west side farmhouse porch



Figure 12: Detail of scrollwork on west side farmhouse porch



Figure 13: Detail of west side farmhouse porch



Figure 14: Detail of west side farmhouse porch



Figure 15: Detail of Shaver Family well



Figure 16: East Elevation of c. 1830 frame house



Figure 17: South Elevation of c.1830 frame house showing workshop extension



Figure 18: North Elevation of c.1830 frame house



Figure 19: Detail of paneled "Loyalist" door



Figure 20: View of c.1856 bakehouse



Figure 21: South Elevation of c.1856 bakehouse



Figure 22: East Elevation of Bakehouse showing rear of bake oven



Figure 23: View of interior of c.1856 bake house, showing hearth and bake oven



Figure 24: North Elevations of outhouse (right) and smokehouse (left)



Figure 25: Rear of outhouse (left) and smokehouse (right)



Figure 26: North Elevation of c.1872 icehouse



Figure 27: View of c.1920 milkhouse



Figure 28: View of Horse Barn (left), Dairy Barn (right) and milkhouse (foreground)



Figure 29: East Elevation of Dairy Barn



Figure 30: North Elevation of Dairy Barn, showing silo and 1942 attached milkhouse



Figure 31: North and East Elevations of Horse Barn



Figure 32: South and East Elevations of Horse Barn



Figure 33: View of pre-1950 shed (left)



Figure 34: View of 1959 Equipment Shed



Figure 35: Interior View of farmhouse showing hand hewn beams



Figure 36: Interior of farmhouse showing framework of beams



Figure 37: Interior of farmhouse showing framework of beams



Figure 38: Interior of farmhouse showing living room



Figure 39: Detail of fireplace in living room of farmhouse



Figure 40: View of front hall in farmhouse



Figure 41: Detail of staircase



Figure 42: Detail of staircase



Figure 43: Interior of Main Entrance



Figure 44: Detail of Medallion in front hall



Figure 45:View of Study



Figure 46: Detail of medallion in study



Figure 47: Detail of trim in study



Figure 48: Farmhouse in 1859 (Map of Wentworth County 1859)




Figure 49: Farmhouse in late nineteenth century (Ancaster: A Pictorial History)



Figure 50: Farmhouse in 1952 (Hamilton Public Library: Local History and Archives)




Figure 51: Farmhouse in 1984 (Ancaster LACAC)



Figure 52: barnyard in 1984 (Ancaster LACAC)