

Photographs

All images taken by City of Hamilton Staff on April 19, 2023, unless otherwise stated.



Image 1: Southern elevation from the south. Note the decorative collar on the top of the building, surrounding mature trees, and circular landscaping surrounding the pedestal base.



Image 2: Northern elevation from the north. Note the four large picture windows facing the rear of the property, and projecting porch enclosed with screens.



Image 3: Northern elevation from the north. Note the surrounding mature trees.



Image 4: Southeastern second storey elevation from the eastern elevated drive and entry way. Note the protected second storey entrance, bridge, and angled decorative fence.



Image 5: Close-up detail of the fence along the second floor entry porch.



Image 6: Close-up detail of the second storey soffits and transom windows.



Image 7: Close-up detail of the cedar board cladding underneath the second storey of the Lennard / Mushroom house.



Image 8: Image of the first storey circular glass bay.



Image 9: Image of landscaping features, including cut stone stairs leading down from the upper level entry way and stone planter.



Image 10: Image of cut stone stairs leading down from the upper level entry way and stone planter.



Image 11: Image of Sydenham Creek, located directly across the street from 7 Rolph Street to the south.



Image 12: Image of the spiral staircase looking down from the second storey.
Photo Credit: "The Lennard House," Historical Hamilton, accessed April 12, 2024,
<https://historicalhamilton.com/dundas/the-lennard-house/>.



Image 13: Image of the spiral staircase banister on the second storey.
Photo Credit: “The Lennard House,” Historical Hamilton, accessed April 12, 2024,
<https://historicalhamilton.com/dundas/the-lennard-house/>.



Image 14: Image of the interior portion of the skylight, located centrally in the building, lined with stained cedar.



Image 15: Image of the stained cedar ceiling, radiating from the center of the building.



Image 16: Image of the stained cedar ceiling in the main living area, extending to the outer walls.



Image 17: Close up detail of the stained cedar ceiling.

