

Tent Service at St. Giles Presbyterian Church, 1908 (Wee Kirks and Stately Steeples: A History of the Presbytery of Hamilton, 1990)




The original Sunday school building, c.1908 (Wee Kirks and Stately Steeples: A History of the Presbytery of Hamilton, 1990)



Front Façade, May 18, 2018




Close up of trefoil detailed caps, May 18, 2018




Front Entrance Close-up, May 18, 2018



West Elevation, May 18, 2018



Close up of West Elevation between bell tower and transept



Close up of Gothic Arched window in west transept, May 18, 2018



West Elevation Gothic arched window and WW1 cairn, May 18, 2018




Bell Tower, May 18, 2018



East Elevation, May 18, 2018



Close up of East elevation addition, May 18, 2018



Close up of East Elevation Side Entrance, May 18, 2018



North Elevation including 1958 addition, May 18, 2018




1958 addition, May 18, 2018




Close up of 1958 addition, May 18, 2018



Close up of 1958 addition, May 18, 2018



Chancel, May 31, 2018



Sanctuary facing west transcept, May 31, 2018



Close up of balcony in sanctuary, May 31, 2018



Wooden trusses, May 31, 2018




Close up of wooden corbel, May 31, 2018




Trefoil pattern in sanctuary pews, May 31, 2018



Close up of wooden light fixture with stained glass, May 31, 2018



Interior window (left view from room behind Chancel, right view from Sanctuary looking at Chancel), May 31, 2018



Stairs on east side of front entrance, May 31, 2018



Bell ringing apparatus, May 31, 2018



Water damage in room above arched entrance on Holton Avenue South, May 31, 2018



Water damage in Memorial addition, May 31, 2018



Basement kitchen, May 31, 2018

Appendix "D" to Report PED18153 Page 20 of 20



Basement near kitchen, May 31, 2018 (black is mold growth)