

FirstOntario Centre


ARENA RENOVATION STUDY



BBB ARCHITECTS

SCI

Stadium Consultants International










BBB ARCHITECTS

OPTION 2 - INTERIOR PERSPECTIVE



OPTION 2 - INTERIOR PERSPECTIVE



FirstOntario
Centre




Hamilton

OPTION 1 - ARENA
RENOVATION STUDY

L1 - EVENT LEVEL



BBB ARCHITECTS
SCI, STADIUM CONSULTANTS
INTERNATIONAL, INC.



SECTION




2009 12 20

BBB ARCHITECTS
SCI STADIUM CONSULTANTS
INTERNATIONAL INC.



OPTION 2 - EXTERIOR PERSPECTIVE



NEW HSS 8x8 ES - TOP CHORD REINFORCEMENT

NEW W8 - BOTTOM CHORD
REINFORCEMENT - TYP.


FIELD BOLTED SPLICE PLATE

NEW HSS 6x5 ES - TOP
CHORD REINFORCEMENT

INTERMITTENT STAGGERED WELD - TYP

NEWWB - BOTTOM CHORD
REINFORCEMENT

INTERMITTENT STAGGERED WELD







OPTION 1



OPTION 2



OPTION 1a



OPTION 4

