

INFORMATION REPORT

| ТО: | Chair and Members General Issues Committee |
|--------------------|--|
| COMMITTEE DATE: | August 10, 2020 |
| SUBJECT/REPORT NO: | Tim Hortons Field – End Guard Anchor Repair/Replacement (PW20039(b)) (City Wide) |
| WARD(S) AFFECTED: | City Wide |
| PREPARED BY: | Rob Gatto (905) 546-2424 Ext. 5448 Janet Warner (905) 546-2424 Ext. 7044 |
| SUBMITTED BY: | Rom D'Angelo Director, Energy, Fleet and Facilities Management Public Works Department |
| SIGNATURE: | Rom D'angelo |

COUNCIL DIRECTION

At the July 6th, 2020 General Issues Committee, staff submitted a report titled Tim Hortons Field-End Guard Anchor Repair/Replacement, PW20039(a) which made the following recommendations:

- (a) That staff be directed to repair and/or replace the perimeter end guards that surround the upper bowl of the east and west stands, along with the north and south upper-lower end guards of Tim Hortons Field at an upset limit of \$1.1 million;
- (b) That Facilities Management use existing Capital Budget WIP'S through appropriation to fund this work by reprioritizing existing projects for the current year.

Council deferred the report for 30 days and directed staff to request an on-site review with both Infrastructure Ontario and the contractor Ontario Sports Solutions.

INFORMATION

Staff sent a letter of invitation to Infrastructure Ontario to come onsite at Tim Hortons Field to inspect the end guard conditions. IO responded that they do not have the technical expertise to comment, and IO extended the invitation to the contractor to

SUBJECT: Tim Hortons Field – End Guard Anchor Repair/Replacement (PW20039(b)) (City Wide) - Page 2 of 2

attend the stadium, which Ontario Sports Solution has accepted. Staff will coordinate a schedule site visit to complete an inspection with the contractor in the near future.

APPENDICES AND SCHEDULES ATTACHED

Not applicable.