Appendix "A" to Report FCS20082(c) / HSC20045(c) / PW22087(a) Page 1 of 1

Location	Scope of Work	Cost (\$1000's)
Upper Sherman Location (729 Upper Sherman)	Upper Sherman Location Subtotal: consulting, fitups, equipment, minor furniture, consoles, corresponding minor infrastructure fit-up, taxes, internal fees, contingency	1108
Central Police Station (155 King William)	Central Police Station Subtotal: consulting, fitups, equipment,minor furniture, consoles, corresponding minor infrastructure fit-up, taxes, internal fees, contingency	800
MATC (1227 Stone Church Rd. East)	MATC consulting & permits	330
MATC (1227 Stone Church Rd. East)	MATC construction (including escalation & contingency), corresponding infrastructure replacement, fit-up, UPS	3150
MATC (1227 Stone Church Rd. East)	MATC Furniture, Consoles	518
MATC (1227 Stone Church Rd. East) & Station 30 (training room only at Rymal Rd. E)	Relocation of legislated training room from MATC to fitup training room at Station 30, corresponding minor infrastructure fit-up within the Station 30 training room	225
MATC (1227 Stone Church Rd. East)	MATC Taxes & Internal Fees & Contingency	693
MATC (1227 Stone Church Rd. East)	MATC subtotal (Addition of all work at MATC)	4916
(Upper Sherman Location Sul	6824	