


Photographic Examples of Residential Drainage Issues

Site 1: Blocked Swale Causing flooding on adjacent property - Images









Site 2: Rear Yard Flooding in an Older Neighbourhood without Grading or Drainage Plans - Images





Site 3: Swale Blocked by Grade Changes on Downstream Property - Images

Appendix "B" to Report PED14105(a) Page 6 of 7

