

Picture 1

3 bowls on top of file cabinet. Filled to brim and continually overflowing into bins and onto floor.

Picture 2

5 Rubbermaid bins filling to brim. Had to be dragged outside to empty on a regular basis.

Bins were not sufficient to catch all the water coming down, resulting in constant water on floor which flooded down to basement. Bins were at least a 65 litre capacity. In total, 7 rubbermaid bins were in use. Emptied 8-10 times over the course of day/evening.

