Construction Photographs

Appendix "A" to Report PW11098(f) Page 1 of 3



Figure 1: Original Biosolids/Incinerator Facility (2017)



Figure 2: Demolition of Existing Facility (2018)



Figure 3: New Biosolids/Wet Sludge Storage Silos (2018)



Figure 4: Structural Steel Construction (2019)



Figure 5: Architectural Installation (2019)



Figure 6: Dry Pellet Storage Silo Construction (2019)

Construction Photographs

Appendix "A" to Report PW11098(f) Page 2 of 3



Figure 7: Facility Interior; Shaker Screen and Separator (2020)



Figure 8: Aerial of Facility Interior, Process Area (2020)



Figure 9: Andritz Drum Dryer (2020)



Figure 10: Final Product, Dry Pellets

Construction Photographs

Appendix "A" to Report PW11098(f) Page 3 of 3



Figure 10: Finished Facility Exterior, North-West Elevation (2020)



Figure 11: Finished Facility Exterior, South Elevation, Product Storage Silo (2020)