

Photo Documentation of 19 Flamboro Street, Flamborough



Image 1: Carson Yard (now 19 Flamboro Street) circa 1960s, looking north up Flamboro Street from the corner of Flamboro and Barton Streets, showing the former brick front facade (Flamborough Archives, BW3871)



Image 2: Carson Yard circa early 1960s (Jonathan Vance via Facebook, Waterdown Memories Group, posted June 8, 2019)



Image 3: Carson Yard circa 1980s, looking north-west from Barton Street across the property towards Flamboro Street (Westra Sjoerd George via Facebook, Waterdown Memories Group, posted September 24, 2018)



Image 4: 19 Flamboro Street front (west) facade clad in stucco, December 2021 (City of Hamilton)





Image 5: 19 Flamboro Street side (south) facade clad in stucco, December 2021 (City of Hamilton)



Image 6: 19 Flamboro Street rear addition, side (south) facade clad in stucco, December 2021 (City of Hamilton)



Image 7: 19 Flamboro Street, rear (east) facade clad in stucco, December 2021 (City of Hamilton)



Image 8: 19 Flamboro Street side (north) concrete-block facade, December 2021 (City of Hamilton)





Image 9: Front commercial entrance, December 2021 (City of Hamilton)



Image 10: Interior commercial office space, December 2021 (City of Hamilton)




Image 11: First interior garage bay looking at north side concrete-block exterior wall, December 2021 (City of Hamilton)




Image 12: First interior garage bay looking west to front exterior wall and garage door, December 2021 (City of Hamilton)





Image 13: Second interior garage bay in rear addition looking north to former exterior concrete-block rear wall of the original building (now an interior wall) and blocked-in window opening with lintel, December 2021 (City of Hamilton)




Image 14: Metal stairwell to upper-floor (private residence) above the commercial office, December 2021 (City of Hamilton)



Image 15: Only remaining hung wood window found in the first-floor bathroom, with two-over-two horizontal wood muntins and modern replacement glass and aluminum exterior storms, December 2021 (City of Hamilton)



Image 16: Location of remaining hung wood window in first-storey bathroom located in rear wing of the original building, December 2021 (City of Hamilton, modified by author)





Images 17 and 18: Remaining interior six-panel wood door located in the entrance to the first interior garage, December 2021 (City of Hamilton)