Photographs



66-68 Charlton Avenue West, South Facing, Front Facade, November 1, 2022



66 Charlton Front Facade, November 1, 2022



68 Charlton Front Facade, November 1, 2022



West Elevation of 68 Charlton Avenue West, facing Park Street, October 21, 2022



North Elevation facing the rear alley, October 21, 2022

Appendix "C" to Report PED22208 Page 5 of 16




Northwest Elevation, October 21, 2022




Southeast Elevation of 66 Charlton Avenue West, November 1, 2022



66 Charlton, South Elevation, close up of projecting pedimented front gable, November 1, 2022



68 Charlton, South Elevation, close up of principle entrance, November 1, 2022



68 Charlton, South Elevation, close up of octagonal slate shingles above entrance, October 21, 2022



68 Charlton, South Elevation, close up of dentilated cornice and wood bracket, November 1, 2022



68 Charlton, South Elevation, close up of decorative brick detailing, November 1, 2022



68 Charlton, West Elevation, close up of projecting gable pediment and three-sided bay, Google Street View, April 2012



68 Charlton, North Elevation, detail of rear retaining wall and boundary stone wall, October 21, 2022




68 Charlton, West Elevation, detail of stone boundary wall, Google Street View, October 2020

Appendix "C" to Report PED22208 Page 14 of 16




68 Charlton, detail of stone boundary wall, November 1, 2022



68 Charlton, South facade, Historical City of Hamilton File Image (circa 1950s)



68 Charlton, Southeast facade, Historical City of Hamilton File Image (circa 1950s)



68 Charlton, Southwest facade, Historical City of Hamilton File Image (circa 1950s)