

Photographs

All images taken by City of Hamilton staff on June 14, 2024 unless otherwise noted.



Figure 1: South elevation in 2013 (City of Hamilton Staff July 2013).



Figure 2: South elevation of subject property.



Figure 3: North and west elevations of subject property showing 1950s additions.



Figure 4: West elevation of subject property.



Figure 5: East elevation of subject property showing 1950s additions (City of Hamilton staff July 2013).



Figure 6: South elevation in 2024.



Figure 7: Detail view of parapet on south elevation (City of Hamilton staff July 2013).



Figure 8: Detail view of parapet rear.



Figure 9: Detail view of entryway on south elevation (City of Hamilton Staff July 2013).



Figure 10: Detail view of entryway on south elevation.



Figure 11: Detail view of brickwork and pseudo-half-timbering (City of Hamilton staff July 2013).



Figure 12: Detail view of windows on west elevation (City of Hamilton staff July 2013).



Figure 13: Detail view of cupola with bell.



Figure 14: Detail view of cupola with bell.