

Photographs

All images taken by City of Hamilton Staff unless otherwise stated.



Image 1: Front (north) elevation (February 21, 2025)



Image 2: Front (north) elevation (February 21, 2025)



Image 3: Front (north) elevation (July 10, 2012)



Image 4: Close-up of the stone balustrade, entablature, and doric capitals (July 10, 2012)



Image 5: Close-up of the dentilated cornice (July 10, 2012)



Image 6: Close up of multi-pane metal windows with decorative metal Roman lattice window grillwork (July 10, 2012)



Image 7: Close-up of the recessed central entrance with stone surround, flanking columns with moulded panels and Doric capitals and entablature (July 10, 2012)



Image 8: Rear (south) elevation (Feb 21, 2025)



Image 9: Historic image of the front (north) elevation, circa 1950. (Hamilton Public Library, Image number 32022189061688, circa 1950)





Image 10: Historic image of the front (north) elevation, circa 1950s. (Hamilton Public Library, Image number 32022189061183, circa 1950s)



Image 11: Historic image of the front (north) elevation, circa 1973. (Hamilton L.A.C.A.C. Flashcard, circa 1973)