

Photographs

All photographs taken by City of Hamilton staff on December 4, 2024, unless otherwise noted.



Figure 1: Central Presbyterian Church from the intersection of Charlton Avenue and Caroline Street. City of Hamilton staff, February 7, 2025.



Figure 2: View of north elevation.



Figure 3: View of south elevation.



Figure 4: View of southwestern corner.



Figure 5: View of Sunday School front (north) elevation.



Figure 6: View of Sunday School rear (south) elevation.



Figure 7: Detail view of spire.



Figure 8: Detail view of spire base.



Figure 9: Detail view of spire top.



Figure 10: Detail view of front (east) elevation.



Figure 11: Detail view of front (east) elevation.




Figure 12: Detail view of doorway on front (east) elevation.



Figure 13: Detail view of carved decorative elements.



Figure 14: Detail view of secondary entrance on front (east) elevation.



Figure 15: Detail view of window surround.



Figure 16: View of side (south) elevation entrance.



Figure 17: Detail view of doorway on side (south) elevation.



Figure 18: Detail view of doorway on side (north) elevation entrance.



Figure 19: Detail view of northwest corner of Sunday School.



Figure 20: Detail view of Sunday School entrance on front (north) elevation.




Figure 21: Central Presbyterian Church in 1913 (Hamilton, Canada: its history, commerce and industries and resources, 1913)



Figure 22: Elevation of subject property by John Lyle, 1907 (John M. Lyle: Towards a Canadian Architecture, 1982).



Figure 23: Elevation of subject property by John Lyle, 1907 (John M. Lyle: Towards a Canadian Architecture, 1982).