

## Photographs

All images taken by City of Hamilton Staff on November 16, 2023 unless otherwise noted.



Figure 1: Front Elevation (east) facing Dartnall Road



Figure 2: View of Subject Property from West





Figure 3: Side Elevation (North) looking along the Chippewa Trail



Figure 4: Side Elevation (South) looking along the Chippewa Trail



Figure 5: Detail View of Roofline and Headhouse



Figure 6: Detail View of Headhouse





Figure 7: Detail View of Maple Leaf Motif stamped on sheeting



Figure 8: Detail View showing roof construction



Figure 9: Detail View showing roof construction



Figure 10: Detail View showing roof construction





Figure 11: Harris Grain Elevation under construction, 1943 (Rymal Station Heritage)




Figure 12: Rail line next to defunct elevator, 1987 (Rymal Station in HO Scale)